

SOLID MINERALS

Albuquerque

STATE NEDATE OF INSPECTION June 12, 1984

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
6 N00-C-14-20-5681	TEDCO	Exploration	1	.5 / 2	Uranium	Lease
7 -8396	"	"	1	.5 / 2	"	"
8				/		
9				/		
10				/		
11				/		
12				/		
13				/		
14				/		
15				/		

17 TYPE OF INSPECTION (CHECK ONE) / / MINE / XX / EXPLORATION / / MINE ABANDONMENT
 18 / / TECH EXAM, EA / / INACTIVE / / OTHER

20 PURPOSE OF INSPECTION Examination of lease operations

22 BRIEF DESCRIPTION OF INSPECTION No activity on lease. Lease in good condition.

25 MINE NAME _____ DESIGNATED OPERATOR _____
 26 DATE ORIGINAL MINE PLAN SUBMITTED _____ DATE ORIGINAL MINE PLAN APPROVED _____
 27 DATE MODIFIED MINE PLAN SUBMITTED _____ DATE MODIFIED MINE PLAN APPROVED _____
 28 IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: _____

31 DATE ORIGINAL EXPL. PLAN SUBMITTED 04/09/76 DATE ORIGINAL EXPL. PLAN APPROVED 06/28/76
 32 DATE MODIFIED EXPL. PLAN SUBMITTED _____ DATE MODIFIED EXPL. PLAN APPROVED _____

34 BLM INSPECTOR(S) AND TITLES(S) George R. Tetreault, Jr., Mining Engineer
George Laskar, Minerals Section Chief

36 SURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

38 NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION _____

39 None

40 NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION _____

41 None

42 NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION _____

43 None

45 HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0

46 HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 1

47 TOTAL TRAVEL TIME 1 hour TOTAL OFFICE TIME 1

49 WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / XX / NO
 50 IF YES, PREPARE NONCOMPLIANCE REPORT

52 WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / XX / NO
 53 IF YES, PREPARE UNDESIRABLE EVENT REPORT

55 PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION
 original:

Area Director, NAO, BIA

George R. Tetreault, Jr.